Intertek Total Quality. Assured. 40 51st Way, Suite 100 Fridley, Minnesota 55421

Telephone: 651-636-3835 Facsimile: 717-764-4129 www.intertek.com/building

SUMMARY TEST REPORT

FOR: Andersen Corporation 100 4th Avenue North Bayport, Minnesota 55003
 Report Number:
 K7457.02-201-44

 Test End Date:
 06/03/2020

 Report Date:
 07/29/2020

 Test Record Retention End Date:
 06/03/2024

Contemporary Clad Wood Stormwatch Folding Outswing Door 6 Panel, 3L3R with

NAFS-17, -11, -08 CSA A440S1-17, -09

Test

SERIES/MODEL TESTED

High Performance Sill Class LC-PG50 Size Tested 220.1 x 119.5 in. DP +50/-50 psf

Results Summary

Operating force Resistance to Air Infiltration Resistance to Water Infiltration Resistance to Structural Loading Forced Entry Resistance 36 N (8 lbf) Force to Latch 0.09 cfm/ft² (ASTM E283) Pass at DP +50 (ASTM E547) Pass at DP +50/-50 (ASTM E330) Pass (AAMA 1304)

Test Dade Co. TAS 201, 202, 203 ASTM E 1886, E 1996 Impact Pressure Cycling

Results Summary

Zone 4, Missile D +50/-50 psf

See Intertek B&C Report No. K7457.01-201-44, K7450.01-201-18, and

K7450.02-201-44 for complete test results.

REFERENCE:

A copy of this report will be retained by Intertek B&C for a period of four years. This report is the exclusive property of the client named herein and is applicable to the sample tested. Results obtained are tested values and do not constitute an opinion or endorsement by

INTERTEK B&C

this laboratory.

INTERTEK B&C

Karl Lips Senior Technician

Daniel A. Johnson Director - Regional Operations

