

## SUMMARY TEST REPORT

FOR:	Eagle Window & Door, Inc.	Report Number:	C7118.03-201-44	
	2045 Kerper Boulevard	Test End Date:	04/24/2013	
	Dubuque, Iowa 52001	Report Date:	06/17/2013	
		Test Record Retention End Date:	04/24/2017	
SERIES TESTED:		4086 Series 07 Talon Single Hung Monume	4086 Series 07 Talon Single Hung Monumental Vent	
NAFS-11		Class LC-PG50 1219 x 2604 (48 x 102	Class LC-PG50 1219 x 2604 (48 x 102)-H	
NAFS-08		Class LC-PG50 1219 x 2604 (48 x 102	Class LC-PG50 1219 x 2604 (48 x 102)-H	
<u>Test</u>		<b>Results Summary</b>		
Resistance to Air Infiltration		0.10 cfm/ft <sup>2</sup> (ASTM E283)	0.10 cfm/ft <sup>2</sup> (ASTM E283)	
Resistance to Water Penetration		Pass at DP50 (ASTM E547)	Pass at DP50 (ASTM E547)	
Resistance to Structural Loading		Pass at DP50 (ASTM E330)	Pass at DP50 (ASTM E330)	
Forced Entry Resistance		Pass at Grade 10 (ASTM F588)	Pass at Grade 10 (ASTM F588)	
CAN/CSA A440-00, Evaluation to the prescriptive requirements were not performed				
<u>Test</u>		Rating	Rating	
Air Tightness		A2	A2	
Water Tightness		B3	B3	
Wind Load Resistance		C3	C3	
Blow-Out		C3	C3	
ASTM	E1886 - 02 & 05			
ASTM	E1996 - 02 & 05			
<u>Test</u>		Results Summary		
Impact			No rips, tears or penetrations	
Pressure Cycling		DP+50/-50		
DEFE		See ATI Report No. C7118.01-201-44, C7118.02-201-44 and C7118.04-201-44		
REFERENCE:		for complete test results.		

A copy of this report will be retained by ATI for a period of four years. This report is the exclusive property of the client named herein and is applicable to the sample tested. Results obtained are tested values and do not constitute an opinion or endorsement by this laboratory.

## ARCHITECTURAL TESTING, INC

## **ARCHITECTURAL TESTING, INC**

Eric J. Schoenthaler Project Manager

Daniel A. Johnson **Director - Regional Operations** 

849 Western Avenue North St. Paul, MN 55117 Phone: 651-636-3835 Fax: 651-636-3843 www.archtest.com